

---

## **Errata: CS42L52 Rev. B0 Silicon**

Reference the CS42L52\_DS680PP1 Data Sheet

---

- ◆ The VP Input Current During Reset does not meet data sheet specification. During reset, the current through the VP supply may exceed 200 uA when VP > 3.7 V.

---

### **Contacting Cirrus Logic Support**

For all product questions and inquiries, contact a Cirrus Logic Sales Representative.  
To find the one nearest you, go to <http://www.cirrus.com>